

# Care Instructions

## **Cast Iron Baths and Basins:**

Use a solution of soapy water and apply with a soft cloth or sponge in a brushing motion. Do not use wire brushes, steel wool & abrasive sponge pads. Rinse thoroughly with water immediately after the application of cleaners and wipe the surface leaving it completely dry after the process.

Do not allow cleaners to sit or soak on the surface and avoid dripping taps.

It is important not to use acidic cleaners or sprays as this will affect the surface of the bath and may result in small brown particles building up on the enamel surface or staining.

## **Copper, Nickel and Brass Baths and Basins:**

Clean with warm soapy water and a non-abrasive cloth and dry immediately after use. Avoid dripping taps, sharp objects and the use of abrasive and harsh chemicals and do not allow hand soaps to remain in contact with the surface.

To keep the item tarnish free re-apply a suitable wax seal regularly every 4-6 weeks depending on use. If the wax has worn off and tarnish presents itself on copper, clean the item with Autosol metal cleaner according to the manufacturer's instructions and then re-apply the wax. Do not use Autosol metal cleaner on nickel plated items and do not allow wet cloths to remain in contact with the surface.

To keep nickel tarnish free the wax seal should be maintained by regular reapplication. If you are in any doubt please contact the retailer who you purchased the item from before attempting to use any cleaning products.

If you are in any doubt please contact the retailer who you purchased the item from before attempting to use any cleaning products.